

EXHIBIT E-3

Galli Group

Photo Log of Failing Embankments



PHOTO 1: Note Undermining of Footing



PHOTO 2: Seawall with Scour Beneath Footing

PHOTO 3:

PHOTO 4:

PHOTO 5:

PHOTO 6:

PHOTO 7:

PHOTO 8:

PHOTO 9:

PHOTO 10:

PHOTO 11:

PHOTO 12:

PHOTO 13:

PHOTO 14:

PHOTO 15:

PHOTO 16:

PHOTO 17:

PHOTO 18:

PHOTO 19:

PHOTO 20:

PHOTO 21:

PHOTO 22:

PHOTO 23:

PHOTO 24:

PHOTO 25:

PHOTO 26:

PHOTO 27:

PHOTO 28: